



## STAR ONLINE PUBLICATION



**Case Number:** S2213000001

**Release Date:** June 2022

**Symptom/Vehicle Issue:** Frame Bracket Attached To Right Front Frame Rail Behind Front Tire.

**Customer Complaint/Technician Observation:** Owner and technician may be curious what the bracket is shown in the image below.

**Discussion:**



Bracket on right front frame behind front tire.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found**



## STAR ONLINE PUBLICATION



The bracket shown above is only on the right front. There will be no bracket on the left front. This bracket is for side impact offset ridged barrier performance or also known as a SORB bracket. It is not to be removed and is part of the crash safety system of the vehicles frame.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found**