

**ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager**

Freightliner Dealers – U.S. and Canada  
Western Star and Sterling Dealers – U.S. and Canada  
FCCC Dealers – U.S. and Canada  
Thomas Built Buses Dealers – U.S. and Canada  
Direct Warranty Customers – U.S. and Canada  
Detroit Diesel Distributors  
Export Distributors

Daimler Truck North America LLC

**WARRANTY CAMPAIGNS DEPARTMENT**

P.O. Box 4090 800-547-0712  
Portland, Oregon 97208-4090

If you have questions about this Letter, please submit your inquiry on the Web using the [WSC Link on DTNAConnect](#)

REF #: ICI22-043

Effective: 09/26/2022

Release: 09/26/2022

**SUBJECT: SF633 – Revised Bulletin**

This letter is to inform you that a revised bulletin for Field Service SF633 FCCC School Bus Chassis Park Brake Alarm is available on DTNAConnect. Please print and use the revised bulletin for all work under SF633 from this point forward.

**REVISION:** Due to a software parameter change that was not updated at the host, the SF633 repair provided during August 2021 through August 2022 was not adequate. The host has been updated and the repair will now rectify the issue. SF633 has been re-released with a new termination date of **September 30, 2023**.

If you have questions or need further information, contact the Warranty Campaigns Department by submitting an inquiry through the WSC link on DTNAConnect.

*The information contained in this letter supercedes and supplements any related policies and procedures in any previously released bulletins, the Warranty Manual, and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.*