



(Back Office) - Cruise Control Inoperative After Updating Software VECU5 Without ESP Package (UESP)



For vehicles built with VECU5 and without the ESP package, the cruise control may not operate following a software update to the VECU.

There is an issue with the Software transition where DOID [P1R90 \(Cruise Control, Deactivation by the Vehicle Dynamic Control \(VDC\) Brake Light Request, Enable\)](#) is set to true where it should be set to False.

This can be set to false with accessory kit **85156084**.



Tags

[mack](#)[volvo](#)[vecu5](#)[cruise control](#)

Related links and attachments

No links or attachments available



Feedback

[Give feedback](#)

to help improve the content of this article