WNL7 Workshop campaign - Retrofitting indicator plate on vehicle electrical system battery

WNL7 Workshop campaign - Retrofitting indicator plate on vehicle electrical system battery

ID Number WNL7

Models Cayenne (9YA/9YB)

Model Years 2022
VIN List Attached
Number of Affected VINs 1,452

Issue Description An indicator plate on the 12V vehicle electrical system

battery was not affixed in the affected vehicles due to

a process error.

This indicator plate contains important information on leak protection for the vehicle electrical system batte-

ry.

For this reason, the indicator plate on the vehicle electrical system battery must be retrofitted in the af-

fected vehicles.

What Dealers Should do Please arrange for this measure to be carried out as

soon as possible on affected vehicles. As of the time of this posting, the repair is immediately available. Parts can be ordered via PPL with no PRMS ticket

needed.

TI Number No. 158-22

Parts required

Designation Quantity/venicle Parts return*	Part number	Designation	Quantity/vehicle	Parts return*
--	-------------	-------------	------------------	---------------

PAB010006A Indicator plate on battery 1 piece No

Warranty processing

Validity:

This workshop campaign will be carried out up to September 8th, 2027 and will be closed on that date. Please note that warranty claims can only be processed up to this date.

Scope 1: Retrofit indicator plate on vehicle electrical system battery

Damage Code WNL7 66 000

Repair Code 1

Labor time 19 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

^{*}The parts must be stored until such time as the related warranty or campaign claim has been credited. If a barcode is generated with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the remanufactured parts process or be scrapped.