

Airstream Service Bulletin

Bulletin Number: 192

Product Line: 2021 & 2022 Basecamp 20

Subject: 2021 & 2022 Basecamp Battery Box Lid Gasket

Operation code: TTSBR8903079

Labor rate will be: .5

It has come to our attention that in certain model year 2021 & 2022 Basecamp 20 travel trailers, the battery box lid gasket was not installed. In certain situations the batteries may have the potential of outgassing, and without the gasket, the gases may enter the living area of the trailer.

Please contact the Airstream Customer Service office at 877-344-1076 ext. 7491 or support@airstream.com, if parts are needed, and they will be sent at no charge.

RANGE OF VEHICLES INVOLVED:

Airstreams built between 7/22/2020 - 4/4/2022

Serial number range: 204844 - 207086

Note: Because our VINs do not run in a contiguous series, there will be units in the VIN range which will not be affected by this Service Bulletin.

Equipment needed:



Cordless drill driver and a
Phillips bit insert



Parts needed:

Foam gasket:
Airstream part number 113238-04




On the Basecamp 20, the battery box is located under the dinette seat, next to the refrigerator cabinet.



The lid has 8 screws holding it to the base. Use a Phillips screwdriver to remove the screws and take the lid off.



The foam tape is self-adhesive, and needs to be applied to the center of the lip, all the way around the lid. Overlap the tape where you started so there are no gaps.



Reinstall the lid, using the 8 screws, and replace the wood cover and cushions.

