

Subject

**2022 Tundra - Oil leak from Rear Differential Pinion Seal**

Market

USA

Service Category

Drivetrain

Section

Axle/Differential

Applicability

2022 Tundra

**APPLICABLE VEHICLES**

2022

Tundra

**CONDITION**

An oil leak from the rear differential pinion seal area is currently under investigation.




**RECOMMENDATIONS**

Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or a holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available workday.

Prior to contacting TAS, attach the following to the case:

1. Photo(s) of the leak area
2. Photo of the Differential Serial Number
3. Photo of Axle Housing Serial Number



**LINK REFERENCES**

This Tech Tip does not contain any link references