



SIB 01 09 21

2022-08-22

G01/G02/G30/G32 NVLD LIMITED WARRANTY EXTENSION TO 15 YEARS/150,000 MILES

This Service Information bulletin (Revision 01) supersedes SI B01 09 21 **dated August 2021**

What's New:

- 2018 X3 xDrive30i, 2019 X4 M40i, 2018 to 2020 530i and xDrive, 2018 to 2019 X3 M40i, 640i, 2018 to 2020 540i and xDrive and the 2019 to 2020 M550i xDrive have been added
- MY 2017 BMW 530i Sedan and xDrive (B460) PZEV/SULEV statement added
- Defect Code updated and the Diagnosis work time labor operation and related contended was added
- The non-qualifying repair statement has been updated.

MODEL

E-Series	MY	Model Description	Production Dates	Engine
G01	2019	X3 sDrive	April 2, 2018 to July 29, 2019	B46
G01	2018 to 2019	X3 xDrive	July 14, 2017 to July 29, 2019	B46
G01	2018 to 2019	X3 M40i	July 12, 2017 to July 28, 2019	B58M
G02	2019	X4 xDrive	May 10, 2018 to July 27, 2019	B46
G02	2019	X4 M40i	October 28, 2017 to July 15, 2019	B58M
G30	2017 to 2020	530i Sedan	October 11, 2016 to June 30, 2020	B46O/D
G30	2017 to 2020	530i xDrive Sedan	October 11, 2016 to June 26, 2020	B46O/D
G30	2018 to 2020	540i Sedan	June 28, 2017 to June 18, 2020	B58M
G30	2018 to 2020	540i xDrive Sedan	June 26, 2017 to June 26, 2020	B58M
G30	2019 to 2020	M550i xDrive Sedan	June 12, 2018 to June 24, 2020	N63R
G32	2018 to 2019	640i xDrive Gran Turismo	June 29, 2017 to June 27, 2019	B58M

Note: The Model information above is for informational purposes only, it is not the only deciding factor.

Note: 2018 X3 xDrive30i, 2019 X4 M40i, 2017 to 2020 530i and xDrive, 2018 to 2019 X3 M40i, 640i, 2018 to 2020 540i and xDrive and the 2019 to 2020 M550i xDrive have been added to this bulletin update as of July 2022

Eligible Vehicles

To assist you in identifying those vehicles that have this component-specific extended limited warranty coverage, the DCSnet Warranty Vehicle Inquiry has been updated with the VIN and Component-specific Vehicle Comment shown below:

Please see SI B01 09 21 (DC 16 13 91 12 00): For this vehicle, the NVLD limited emission-related warranty for defects in materials or workmanship has been extended to 15 years/150,000 miles as determined from the original in-service date. This coverage is subject to the same vehicle eligibility requirements, limitations, and exclusions that apply to the BMW New Vehicle Limited Warranty.

Note: Before performing a repair and submitting a claim, first confirm that the vehicle has the above Notice of Limited Warranty Extension in the DCSnet Warranty Inquiry Vehicle Comments section.

If you have Extended Limited Warranty (ELW) eligibility and/or coverage questions, please contact the Warranty department through IDS by selecting Coverage, Policy, Coding Questions and Mileage Corrections prior to performing any repair.

SITUATION

Component-Specific Limited Warranty Extension



For the eligible vehicles, BMW of North America, LLC (BMW NA) is extending the limited warranty for the vehicle's **Leak Diagnosis Module with hose assembly (NVLD, shown)** to:

- **15 years/150,000 miles as determined by the vehicle's original in-service date.**

For eligible MY 2017 BMW 530i Sedan and xDrive (B460) vehicles that are currently registered in the State of California (CA) or a State that has fully adopted the State of California PZEV/SULEV regulation (CT, ME, MD, MA, NJ, NY, RI, and VT), the standard "component-related" coverage for the NVLD is 15 years/150,000 miles.

This component-specific limited warranty extension applies to defects in materials or workmanship.

This coverage is subject to the same vehicle eligibility requirements, limitations, and exclusions that apply to the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Note: This bulletin is notice of a limited warranty extension. This is NOT a notice of a Recall or Service Action.

There is no immediate repair required unless the BMW vehicle is currently experiencing this problem.

Customer Notification Letter

Even though this is NOT a Recall, BMW NA is sending VIN-specific customer notification letters.

CAUSE

Over time, the Leak Diagnosis Module (NVLD) (with connected hose) component material may fail, this can create a fine leak to develop in the Evaporative Emission Control System (EVAP). Should this occur, corresponding fault codes will be stored in the DME memory and the MIL (Malfunction Indicator Lamp) will illuminate.

CORRECTION

Follow the instructions in the PROCEDURE section.

PROCEDURE

If an applicable Model vehicle arrives at your center with the issue described above, perform the corresponding diagnosis, and replace the NVLD assembly as determined and/or as instructed.

Additionally, any other repair that requires the replacement of the NVLD due to a defect in material and workmanship is also covered under the extended time and mileage limits described in this bulletin.

PARTS INFORMATION

Please refer to the Electronic Parts Catalog (ETK/EPC), using the customer's VIN to locate the applicable replacement part numbers.

Part Number	Description	Quantity
Refer to ETK	Venting line with leak diagnosis module	1

- Only order these **parts in the quantities needed** to address customers' vehicles that have confirmed failures.
- **Only in conjunction with parts:** When applicable, if ETK/EPC item identifies additional part(s) that must also be replaced/installed in-conjunction with performing a covered repair, these required additional items are also covered under the terms of this extended limited warranty.
- Also refer to ETK/EPC and the repair instructions for onetime-use fasteners/screws and other information regarding repair-related gaskets, seals, fluid and/or lubricants that also need to be replaced/used and claimed.

CLAIM INFORMATION

This component-specific limited warranty extension to 15 years/150,000 miles applies to eligible US-specification BMW vehicles that are registered, operated, and have their covered repair performed by an authorized BMW center in the United States (including Puerto Rico) for defects in materials or workmanship.

For eligible MY 2017 BMW 530i Sedan and xDrive (B460) vehicles that are currently registered in the State of California (CA) or a State that has fully adopted the State of California PZEV/SULEV regulation (CT, ME, MD, MA, NJ, NY, RI, and VT), the standard "component-related" coverage for the NVLD is 15 years/150,000 miles.

This component-specific extended limited warranty coverage is subject to the same corresponding vehicle eligibility requirements, limitations, and exclusion criteria that applies to all repairs that will result with a claim submission to BMW.

The existing limited warranty coverage for the whole vehicle and other components has not changed.

This coverage supersedes the coverage that is provided under the BMW Certified Pre-Owned Program or any BMW Group Vehicle Service Contract that applies to the vehicle.

Should the front oxygen sensor fail again, it is covered by the remaining portion of the extended limited warranty coverage period.

Non-Qualifying Repairs

Repairs performed on ineligible vehicles, eligible vehicles operated and repaired outside the United States and Puerto Rico, and/or the diagnosis and repair of issues beyond the scope of this component-specific coverage, or that are due to outside influences, or any other unrelated issues are not covered by this limited warranty extension. This exclusion also applies to repairs that were performed using (including those repairs that result from using) non-genuine BMW parts and/or used BMW passenger car or light truck parts.

Qualifying Repairs – Claim Submission, as determined by the Original In-Service Date

Defect Code:	1613911200	G0x G3x US version leak diagnosis system NVLD
---------------------	-------------------	--

Refer to AIR for the corresponding flat rate unit (FRU) allowances.

Labor Operation	Description	Labor Allowance
00 00 006	Performing vehicle test (with vehicle diagnosis system – checking faults) (Main work)	Refer to AIR
Or:		
00 00 556	Performing vehicle test (with vehicle diagnosis system – checking faults) (Plus work)	Refer to AIR
And:		

61 21 528	Support voltage of the vehicle electrical system / recharge vehicle electrical system battery	Refer to AIR
And, as necessary:		
61 00 006*	Performing vehicle diagnosis – test module (Work time)	(WT)
Or		
00 58 500*	Diagnosis Worktime Flat Rate (See below)	2 FRU
And, as necessary:		
16 00 510	Leak detection on fuel tank and tank ventilation system (Work time)	5 FRU
And:		
16 13 523	Removing and installing/replacing diagnostic module for tank leaks for Natural Vacuum Leak Detection (NVLD)	Refer to AIR

If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead of 00 00 006, or exclude (including 61 21 528) when the Vehicle Test is included in another repair.

Work time labor operation code 61 00 006, 00 58 500 and 16 00 510 are not considered Main labor operations.

*Based on which one applies to your center, please refer to [SI B01 01 20](#) or [B01 07 20](#) for the applicable procedure for documenting, claiming, and explaining, on the RO and in the claim comments, your diagnosis work time (WT), job/repair work time (WT), and the vehicle repairs your center performed, unless otherwise required by State law.

Previous Customer-Pay Repairs – Limited Warranty Extension Reimbursement

BMW of North America, LLC (BMW NA) will provide reimbursement for qualifying customer-pay repairs that were performed on an eligible vehicle **prior** to the release of this component-specific limited warranty extension.

Note: 2018 X3 xDrive30i, 2019 X4 M40i, 2017 to 2020 530i and xDrive, 2018 to 2019 X3 M40i, 640i, 2018 to 2020 540i and xDrive and the 2019 to 2020 M550i xDrive have been added to this bulletin update as of July 2022

Customer-pay repairs are subject to the same vehicle eligibility requirements, limitations, and exclusions that apply to the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Repairs that Do Not Qualify for Reimbursement

Repairs performed on ineligible vehicles, eligible vehicles operated and repaired outside the United States and Puerto Rico, and/or the diagnosis and repair of issues beyond the scope of this component-specific coverage, or that are due to outside influences, or any other unrelated issues are not covered by this limited warranty extension. This exclusion also applies to repairs that were performed using (including those repairs that result from using) non-genuine BMW parts and/or used BMW passenger car or light truck parts.

Requesting Reimbursement for a Previous Repair That Qualifies

For a customer to request reimbursement for a qualifying customer-pay repair performed either by an authorized BMW center or independent repair shop located in the United States (including Puerto Rico), please have him/her submit his/her reimbursement request online at www.BMW-RP.com under the following reference:

- B-ELWR NVLD 15Y150M

Reimbursement Request Procedure

The online process is initiated by attaching/sending PDF files of the supporting documentation for the prior repair.

The letter also includes alternative methods to request reimbursement, either through the mail or by fax as described below:

BMW Customer Reimbursement Center
 Attention: B-ELWR NVLD 15Y150M
 P.O. Box 54067
 Hurst, Texas 76054

Fax number: 877-434-2992

Please allow 4-6 weeks for processing your request.

Should you have any questions concerning this reimbursement process, please call 1-844-857-0341.

FEEDBACK REGARDING THIS BULLETIN

Technical Feedback	To submit feedback for the technical topics of this bulletin: Submit your feedback in the rating box at the top of this bulletin
Warranty Feedback	To submit feedback for the CLAIMS section of this bulletin: Submit an IDS ticket to the Warranty Department, or use the chat available in the Warranty Documentation Portal
Parts Feedback	To submit feedback for the PARTS section of this bulletin: Submit an IDS ticket to the Parts Department

Supporting Materials

[picture_as_pdf B01 09 21 Cust Sample Letter \(8_2022\).pdf](#)

[picture_as_pdf B01 09 21 Cust Sample Letter.pdf](#)



BMW

47911 HALYARD DRIVE
STE. 200
PLYMOUTH, MI 48170
DO NOT MAIL REPAIR ORDERS TO THIS ADDRESS

030458-T1-P1-000001

Sample
Sample
Sample



August 2022

This **“Important Limited Warranty Information,”** effective with the date listed above, applies to the BMW model with the Vehicle Identification Number (VIN) of **5UXTR9C52K1234567.**

Dear BMW Owner/Lessee:

BMW is committed to delivering the ultimate in product satisfaction to our customers.

Towards that end, BMW is extending the limited warranty for the:

- **Leak Diagnosis Module (NVLD) with attached hose assembly**

On the above-referenced vehicle to:

- **15 years/150,000 miles, as determined from your vehicle’s original in-service date.**

This component-specific limited warranty extension applies to defects in materials or workmanship. This coverage is subject to the same vehicle eligibility requirements, limitations, and exclusions that apply to the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Note: If you have an eligible MY 2017 BMW 530i (B460) that is currently registered in the State of California (CA) or a State that has fully adopted the State of California PZEV/SULEV regulation (CT, ME, MD, MA, NJ, NY, RI, and VT), the standard “component-related” coverage for the NVLD is 15 years/150,000 miles.

This is a notice of a “component-specific limited warranty extension.” It is not a notice of a Recall or Service Action.

If a repair to this component is required, please contact your nearest authorized BMW center in the United States or Puerto Rico to schedule an appointment.

Your BMW center will confirm your vehicle’s eligibility and review the scope of the repairs to determine if this “component-specific” extended limited warranty coverage applies. After vehicle inspection and diagnosis, the eligible repair work will be performed by the authorized BMW center free of charge.

Repairs performed on ineligible vehicles, eligible vehicles operated and repaired outside the United States and Puerto Rico, and/or the diagnosis and repair of other unrelated issues are not covered by this component-specific limited warranty extension. This exclusion also applies to repairs, including consequential, that were performed using non-genuine BMW parts and/or used passenger car or light truck parts.

The integrity of our products is essential to BMW’s success and our customers’ trust. We are determined to exceed your expectations and hope this warranty extension further enhances your ownership experience.

Sincerely,

BMW of North America, LLC

B-ELW NVLD 15Y150M (2022) (Sample)

Company
BMW of North America, LLC
BMW Group Company

Mailing Address
PO Box 1227
Westwood, NJ
07675-1227

Website
www.bmwusa.com



Previous Customer-Pay Repairs – Limited Warranty Extension Reimbursement

BMW of North America, LLC

August 2022

VIN 5UXTR9C52K1234567

For the BMW model with the Vehicle Identification Number (VIN) listed above, BMW of North America, LLC (“BMW NA”) will reimburse “qualifying customer-pay repairs” that were performed **prior** to the release of this component-specific limited warranty extension.

Customer-pay repairs are subject to the same vehicle and coverage eligibility requirements, exclusions and limitations that apply to the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Repairs that Do Not Qualify for Reimbursement

Repairs performed on ineligible vehicles, eligible vehicles operated and repaired outside the United States and Puerto Rico, and/or the diagnosis and repair of other unrelated issues are not covered by this component-specific limited warranty extension. This exclusion also applies to repairs, including consequential, that were performed using non-genuine BMW parts and/or used passenger car or light truck parts.

Requesting Reimbursement for a Previous Repair That Qualifies

If you previously had a “qualifying customer-pay repair” performed either by an authorized BMW center or independent repair shop located in the United States (including Puerto Rico), please submit your reimbursement request “online” at www.BMW-RP.com under the following reference:

Covered Component Code

B-ELWR NVLD 15Y150M

To initiate the online process, you will be asked to attach PDF files of the required documentation as outlined in the reimbursement checklist on the next page.

Alternative Method to Request Reimbursement

Alternatively, you may mail or fax your request and documentation to:

BMW Customer Reimbursement Center
Attention: B-ELWR NVLD 15Y150M
P.O. Box 54067
Hurst, TX 76054

Fax number: 877-434-2992

Please allow 4-6 weeks for processing your request.

Should you have any questions concerning this reimbursement process, please call 1-844-857-0341.



BMW Leak Diagnosis Module (NVLD): Limited Warranty Extension to 15 Years/150,000 Miles

Previous Customer-Pay Repair Reimbursement – Documentation Checklist

BMW of North America, LLC

Reimbursement is available to the BMW Owner/Lessee who incurred the expense.

When submitting a reimbursement for a previous repair, please provide **legible** copies (either a scan, photo, PDF, and/or screenshots) of the following documentation with your name, address, and your preferred contact telephone number(s) and email addresses:

Repair Order (RO) or Invoice

This document should include the following information:

- Customer name and address
- Vehicle Identification Number (“VIN”)
- The date of repair
- The mileage when the repair was performed
- Itemized breakdown of the labor charges for all repairs* including diagnosis
- Itemized breakdown of the parts, including any miscellaneous items, billed for all repairs*

*For repair orders containing multiple repair line items, reimbursement consideration will only be given to those line-item expenses that are directly related to the specific repair that is now covered by this component-specific extended limited warranty.

Proof of Payment

In addition to the above, please provide a copy of at least **one** of the following items as valid proof of payment:

- Repair order (RO)/invoice stamped and dated as “PAID”
- Cancelled check
- Signed credit/debit card receipt
- Credit/debit card statement

Unreadable, altered/modified, incomplete and/or non-authentic documentation **will not** be accepted.

Determining if an eligible vehicle’s repair qualifies for reimbursement:

Please use the following questions to review your repair order documentation prior to submitting a reimbursement request:

1. Why was the vehicle brought into the repair facility?
2. What was the repair facility's diagnosis?
3. What did the repair facility do to correct the concern, and does it qualify?



Leak Diagnosis Module (NVLD): Limited Warranty Extension to 15 Years/150,000 Miles

Frequently Asked Questions (FAQ)

1. With this announcement, which BMW Group US models are potentially eligible for this component-specific Limited Warranty Extension?

E-Series	Model Years	Model Description	Engine
G01	2018	X3 xDrive30i	B46O
G01	2018 to 2019	X3 M40i	B58M
G02	2019	X4 M40i	B58M
G30	2017* to 2020	530i Sedan	B46O
G30	2017* to 2020	530i xDrive Sedan	B46O
G30	2018 to 2020	540i Sedan	B58M
G30	2018 to 2020	540i xDrive Sedan	B58M
G30	2019 to 2020	M550i xDrive Sedan	N63R
G32	2018 to 2019	640i xDrive Gran Turismo	B58M

2. What is the specific issue with the Leak Diagnosis Module (NVLD)?

Over time, the Leak Diagnosis Module component material may fail, this can cause a fine leak to develop in the Evaporative Emission Control System (EVAP).

3. How does this affect my vehicle?

Your vehicle will store the corresponding fault codes that may also be generated, and the Malfunction Indicator Lamp (MIL) will illuminate.

4. What should I do if I notice a similar condition in my vehicle?

Please contact an authorized BMW center in the United States (including Puerto Rico) to have your vehicle inspected, and as necessary, repaired.

5. How will my vehicle be repaired?

If it is determined that due to a defect in materials or workmanship your vehicle's Leak Diagnosis Module has the issue described above, it will be replaced free of charge under the terms of this 15 year/150,000-mile extended limited warranty coverage.

*If you have an eligible MY 2017 BMW 530i (B46O) that is currently registered in the State of California (CA) or a State that has fully adopted the State of California PZEV/SULEV regulation (CT, ME, MD, MA, NJ, NY, RI, and VT), the standard "component-related" coverage for the NVLD is 15 years/150,000 miles.





47911 HALYARD DRIVE
 STE. 200
 PLYMOUTH, MI 48170
 DO NOT MAIL REPAIR ORDERS TO THIS ADDRESS



014577-T1-P1-000001

Sample
 Sample
 Sample



August 2021

This **“Important Limited Warranty Information”** applies to the BMW model with the Vehicle Identification Number (VIN) of **5UXTR9C52KL123456**.

Dear BMW Owner/Lessee:

BMW is committed to delivering the ultimate in product satisfaction to our customers.

Towards that end, BMW is extending the limited warranty for the:

Leak Diagnosis Module (NVLD) with hose assembly

On the above-referenced vehicle to:

- **15 years/150,000 miles, as determined by your vehicle’s original in-service date.**

This “component-specific” limited warranty extension applies to defects in materials or workmanship. This coverage is subject to the same vehicle eligibility requirements, limitations, and exclusions that apply to the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

This is a notice of a “limited warranty extension.” It is not a notice of a Recall or Service Action.

If a repair to this component is required, please contact your nearest authorized BMW center in the United States or Puerto Rico to schedule an appointment.

Company
 BMW of North America, LLC
 BMW Group Company

Mailing Address
 PO Box 1227
 Westwood, NJ
 07675-1227

Telephone
 (800) 831-1117

E-mail
 Customerrelations@
 bmwusa.com

Website
 www.bmwusa.com

Your BMW center will confirm your vehicle’s eligibility and review the scope of the repairs to determine that this extended limited warranty coverage applies. After vehicle inspection and diagnosis, eligible repair work will be performed by the authorized BMW center free of charge.

Repairs performed on ineligible vehicles, eligible vehicles operated and repaired outside the United States and Puerto Rico, and/or the diagnosis and repair of other unrelated issues are not covered by this limited warranty extension. This exclusion also applies to repairs, including consequential, that were performed using non-genuine BMW parts and/or used passenger car or light truck parts.

The integrity of our products is essential to BMW’s success and our customers’ trust. We are determined to exceed your expectations and hope this warranty extension further enhances your ownership experience.

Sincerely,

BMW of North America, LLC



Previous Customer-Pay Repairs – Limited Warranty Extension Reimbursement

BMW of North America, LLC

Month 2021

VIN 5UXTR9C52KL123456

BMW of North America, LLC (“BMW NA”) will provide reimbursement for “qualifying customer-pay repairs” that were performed on an eligible vehicle prior to the release of this component-specific limited warranty extension.

Customer-pay repairs are subject to the same vehicle and coverage eligibility requirements, exclusions and limitations that apply to the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Repairs That Do Not Qualify for Reimbursement

Repairs performed on ineligible vehicles, eligible vehicles operated and repaired outside the United States and Puerto Rico and/or the diagnosis and repair of other unrelated issues. This exclusion also applies to repairs, including consequential, that were performed using non-genuine BMW parts and/or used passenger car or light truck parts.

Requesting Reimbursement for a Previous Repair that Qualifies

If you previously had a “qualifying customer-pay repair” performed either by an authorized BMW center or independent repair shop located in the United States (including Puerto Rico), please submit your reimbursement request “online” at www.BMW-RP.com under the following reference:

Covered Component Code

B-ELWR 2021 NVLD 15Y150M

To initiate the online process, you will be asked to attach PDF files of the required documentation as outlined in the reimbursement checklist on the next page.

Alternatively, you may mail or fax your request, and documentation to:

BMW Customer Reimbursement Center
Attention: B-ELWR 2021 NVLD 15Y150M
P.O. Box 54067
Hurst, TX 76054

Fax number: 877-434-2992

Please allow 4-6 weeks for processing your request.

Should you have any questions concerning this reimbursement process, please call 1-844-857-0341.



G01, G02 NVLD: Limited Warranty Extension to 15 Years/150,000 Miles

Previous Customer-pay Repair Reimbursement – Documentation Checklist

BMW of North America, LLC

Reimbursement is available to the BMW Owner/Lessee who incurred the expense.

When submitting a reimbursement for a previous repair, please provide **legible copies** of the following documentation and include your VIN, name, address and your preferred contact telephone number(s):

Repair Order (RO) or Invoice

This document should include the following information:

- Customer name and address
- Vehicle Identification Number (“VIN”)
- The date of repair
- The mileage when the repair was performed
- Itemized breakdown of the labor charges for all repairs* including diagnosis
- Itemized breakdown of the parts, including any miscellaneous items, billed for all repairs*

*For repair orders containing multiple repair line items, only the specific line item expenses that relate to the component that is covered by this extended limited warranty will be considered for reimbursement.

Proof of Payment

Please provide a copy of at least **one** of the following items as valid proof of payment:

- Repair order (RO)/invoice stamped and dated as “PAID”
- Copy of a cancelled check
- Copy of a signed credit/debit card receipt
- Copy of a credit/debit card statement

Determining if an eligible vehicle’s repair qualifies for reimbursement:

Please use the following questions to review your repair order documentation prior to submitting a reimbursement request:

1. Why was the vehicle brought into the repair facility?
2. What was the repair facility's diagnosis?
3. What did the repair facility do to correct the concern, and does it qualify?



G01, G02 NVLD: Limited Warranty Extension to 15 Years/150,000 Miles

Frequently Asked Questions (FAQ)

1. Which BMW Group US models are potentially eligible for this component-specific Limited Warranty Extension?

E-Series	MY	Model Description	Engine
G01	2019	X3 sDrive30i	B46
G01	2019	X3 xDrive30i	B46
G02	2019	X4 xDrive30i	B46

1. What is the specific issue with the Leak Diagnosis Module (NVLD)?

Over time, the Leak Diagnosis Module (NVLD) component material may fail, this can cause a fine leak to develop in the Evaporative Emission Control System (EVAP).

2. How does this affect my vehicle?

Should this specific issue occur, your vehicle will store the corresponding fault codes that will be generated, and the MIL (Malfunction Indicator Lamp) will illuminate.

3. What should I do if I notice a similar condition in my vehicle?

Please contact an authorized BMW center in the United States (including Puerto Rico) to have your vehicle inspected, and as necessary, repaired.

4. How will my vehicle be repaired?

If it is determined that the NVLD assembly in your vehicle is causing an issue as described above, it will be replaced free of charge under the terms of this 15 year/150,000-mile extended limited warranty coverage.

