



Bulletin No.: PIT5947
Published date: 09/26/2022

Preliminary Information

PIT5947 No Selection To Reset The Fuel Filter Life In The DIC

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade Models	2022	All	All	3.0L LM2	All

Involved Region or Country	North America
Condition	Some customers may comment that they are unable to reset the fuel filter monitor system. When scrolling through the DIC there is no selection for fuel filter life reset.
Cause	Calibration

Correction:

Currently, Engineering is working on a correction and when one becomes available this PI will be updated. In the meantime, for fuel filter maintenance please follow the "Maintenance Schedule" located in the "Cadillac 3.0L Duramax Diesel Engine Supplement" owner's manual.

Version History

Version	1
Modified	09/26/2022 - Created on.

