



Bulletin No.: PIT5951
Published date: 09/28/2022


Preliminary Information

PIT5951 Ink On Body Panels After Removing Protective Wrap

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Envision	2022	All	All	All	All

Involved Region or Country	North America
Condition	Some customers may comment that the writing on the plastic hood wrap has bled through into the paint.
Cause	The plant used the wrong type of marker for this operation.



Example of ink transfer from protective wrap

Correction:

Clean the marker from the hood with Acrysol or equivalent , multiple applications may be needed to remove all the ink.

Parts Information

Contact Kent Automotive at 1-888-YES-KENT, or online at www.kent-automotive.com.

Description	Part Number	Quantity
Kent Automotive Acrysol	P20005	N/A

Version History

Version	1
Modified	09/28/2022 - Created on.



© 2022 General Motors. All Rights Reserved.