

GPOP - Issue Review System

Part Number:

68401895A\$,68401549A\$,68401379A\$,68401396A\$,68401935A\$,68474744A\$,68474259A\$,68474903A\$,68544665A\$,68475245A\$,68440449A\$,68440438A\$,68440435A\$,68400404A\$,68400499A\$,68400545A\$,68400554A\$,68400720A\$,68400737A\$,68376922A\$,68376923A\$,68376924A\$,68376925A\$,68376926A\$,68477135A\$,68477357A\$,68536536A\$

Part Description:

Axle Assembly

**Issue
Description**

A parts kit (SENSOR KIT, Axle: 68544629A\$) is available to repair the Axle Locker Sensor on JL/JT equipped with the M210 and M220 Tru-Lok axles (DSE). This parts kit must be used when only the Axle Locker Sensor fails. Do not replace the axle for sensor failure.