



Service Bulletin

Bulletin No.: 22-NA-202

Date: October, 2022

INFORMATION

Subject: Information on Data Link Connector

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	6500XD/7500XD Medium Duty (LCF)	2022	2022			LCB	


Involved Region or Country	United States
Additional Options (RPOs)	Equipped with 6.7L Engine (RPO LCB)

Service Procedure

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

The Chevrolet Low Cab Forward 6500XD/7500XD with the 6.7L Cummins uses a different data link connector (DLC).

EL-53192 is required to connect the MDI2 to the round diagnostic connector in order to read data and diagnose the vehicle on 6500XD/7500XD low cab forward trucks with the 6.7L Cummins. EL-53192 is needed to ensure the correct pins are used to process data through the DLC to the MDI2.



6174073



6174075

Version	1
Modified	Released October 24, 2022

