

WNT2 Stop delivery - Checking brake line on hydraulic unit and replace if necessary

WNT2 Stop delivery - Checking brake line on hydraulic unit and replace if necessary

ID Number	WNT2
Models	Panamera (971)
Model Years	2023
Number of Affected VINs	4
VIN list	Attached
Summary	<p>On the affected vehicles, there is a possibility that a brake line has been installed on the hydraulic unit that does not meet the required specifications.</p> <p>For this reason, the brake line on the hydraulic unit must be checked on the affected vehicles before vehicle delivery and replaced depending on the test result.</p>
What Dealers Should do	<p>Please do not deliver the subject vehicles until the repair is completed.</p> <p>The vehicles may be driven only for loading and unloading purposes in the transport chain prior to remedy.</p>
TI Number	TI to be posted at a later date.

Important information

DEALERS SHOULD NOT SELL, LEASE, RENT, OR LOAN ANY NEW VEHICLES IN DEALER INVENTORY AFFECTED BY THIS NOTIFICATION PRIOR TO REMEDY. DEALERS

WNT2 Stop delivery - Checking brake line on hydraulic unit and replace if necessary

**GROUNDING LEASE RETURNS SHOULD REMEDY ALL
AFFECTED GROUNDED VEHICLES.**