

**Subject: Engineering Information - (EI Lite) - (Pictures Only) - Squeal Type Noise Heard from Dust Shield Making Contact with the Front Rotor**

*This PI has been revised to end the need for gathering information from the field. Please discard PIE0712.*

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado	2022	2022	—	—	—	—
GMC	Canyon						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

<b>Version</b>	2
<b>Modified</b>	Released July 28, 2022 Revised November 01, 2022 - Ended the need for gathering further information from the field.