

Customer Notification



Corporate Compliance
Po Box 30
MIDDLEBURY, INDIANA 46540-9218

INTERIM OWNER NOTIFICATION

FR ID: 51-1569
Ford Recall: 22S68

<<OWNER NAME/DEALERNAME>>
<<ADDRESS>>
<<CITY>>, <<ST>> <<ZIP-XXX>>

- o Integrity
- o Safety
- o Quality
- o Customer Service

A SECONDARY NOTICE WILL FOLLOW
WHEN THE REMEDY IS AVAILABLE

November 2022

This Notice applies to your vehicle VIN listed above.

Dear Forest River Customer:

Forest River is alerting you to a Ford Recall 22S68 involving certain 2023 Entrada Class A Motorhomes, Forester and Sunseeker Class C Motorhome Recreational Vehicles. Please see the information below, which describes the issue and provides you with details on the steps you should take to have your vehicle repaired.

WHAT IS THE ISSUE?

Some of the affected vehicles may have an improperly torqued bolt that secures the rear axle rotor to the wheel-hub. An improperly torqued bolt in the rotor/ hub assembly can potentially result in slippage at this joint. This can lead to a loss of wheel attachment during hard acceleration or hard brake application events, increasing the risk of a crash.

DEALERS: WHAT SHOULD YOU DO?

Please review and follow the notice that accompanies this letter

DO NOT DEMONSTRATE OR DELIVER any new in-stock vehicles involved in this safety recall. An initial Dealer Bulletin with inspection procedures will be provided to dealers in November. A complete dealer bulletin will be provided to dealers early first quarter 2023 when it is anticipated that parts ordering information and repair instructions will be available to support this safety recall.

IMPORTANT: Dealers should open a Repair Order (RO) only when a full dealer bulletin is published. Opening an RO against an Awareness or Advance Notice will result in warranty rejections against a recall.

OWNERS: WHAT SHOULD YOU DO?

The remedy for this recall is not available at this time. A second notice will be sent when it becomes available.

Sincerely,

Forest River
Office of Corporate Compliance