



# Preliminary Information

## PIP5878 3.0L LZ0 Exhaust Particulate Matter (PM) Sensor Part Restriction

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado	2023	All	All	3.0L LZ0	All
GMC	Sierra	2023	All	All	3.0L LZ0	All

Involved Region or Country	North America
Condition	As part of our ongoing quality improvement efforts the exhaust particulate matter sensor (PM sensor), part number 40009127, will be placed on a parts restriction through the Product Quality Center (PQC).
Cause	This parts restriction will assist Engineering with product feedback.

**Correction:**

**U.S Dealers:**

Please contact the Product Quality Center (PQC) by opening a new case via Dealer Case Management (DCM).

From the DCM home page, click on "New PQC Case" found on the Technical Assistance tab.

Then in Global Connect, click on the Support/Chat tab, TAC-PQC Tab, PQC - Parts Restrictions Templates to download the appropriate PQC - Parts Restrictions Template and save a copy to your computer.

You can attach a copy of the template to your PQC Case.

**Dealers in Canada :**

If your diagnosis leads to a possible part replacement, please contact the PQC by email at PQC@gm.com or by calling 1-866-654-7654 to receive the PQC -Parts Restriction Template then, return the completed Parts Restriction Questions for engineering review.

**Note: Do not clear any DTCs prior to contacting the PQC.**

Parts Information

Description	Part Number	Quantity
Exhaust Particulate Matter (PM) Sensor	40009127	1

Version History

Version	1
Modified	10/14/2022 - Created on.



GENERAL MOTORS

© 2022 General Motors. All Rights Reserved.