



Knowledge

FSC 22-13-2529 Power Steering Hose Update

Edit as Draft

Archive

Article Record Type	Article Number	Publication Status	Last Modified Date	Version Number
Field Service Campaign	000001029	Published	10/17/2022 3:12 PM	3

Details

Related

Versions

Information

Title

FSC 22-13-2529 Power Steering Hose Update

URL Name

FSC-22-13-2529-Power-Steering-Hose-Update

Last Published Date

10/17/2022 3:12 PM

Publication Status

Published

Sharing Public URL

<https://gillig.lightning.force.com/lightning/articles/Knowledge/FSC-22-13-2529-Power-Steering-Hose-Update> (<https://gillig.lightning.force.com/lightning/articles/Knowledge/FSC-22-13-2529-Power-Steering-Hose-Update>).

Field Service Campaign

Issue Description (Rich Text)

GEN2 and GEN2.5 BEBs w/front charger has a possible rubbing concern with Power Steering Pressure hose. No issue w/o front charger GEN2 only has a possible kinking issue with the Power Steering Return hose.

Symptoms (Rich Text)

Chaffing and wear on the pressure hose from front charger HV cable connector body Kinked hose, flow restriction on the return hose

Tools Required (Rich Text)

open end wrenches

Parts Required:

Pressure Hose 46-79637-002 (Gen2/2.5 w/front charger)

Return Hose 46-79636-009 (Gen2 only)

Diagnostic Steps

See Related section for additional details

Repair Steps

Remove and replace the Pressure hose if equipped with front charger port

Remove and replace the Return hose (Gen2 only)

Top off hydraulic fluid

Run bus and check for leaks

Test drive bus checking for correct operation

Labor Information

1 hr

Warranty Claims

Parts Return Disposition

Vendor Article

Visibility

Visible In Internal App

Was this article helpful?



0



0

Categories (0)

Expand All



Visible to Customer

Visible In Public Knowledge Base

Knowledge

FSC 22-13-2529 Power Steering Hose Update

[Edit as Draft](#)

[Archive](#)

Article Record Type	Article Number	Publication Status	Last Modified Date	Version Number
Field Service Campaign	000001029	Published	10/17/2022 3:12 PM	3