

## **SSM 51217**

### **2022 Maverick – Brake Service Mode Inoperative**

Some 2022 Maverick vehicles may exhibit the brake service mode is inoperative when using the Workshop Manual (WSM) procedure. To avoid this condition, do not use the brake service mode procedure described in the WSM. Instead, use Ford Diagnosis and Repair System (FDRS) scan tool to activate the Brake Service Mode. Run the ABS-Electronic Parking Brake (EPB) Service Tools app and select enter park brake maintenance mode.