



# Technical Service Bulletin

---

## 68 Wind deflector bearing and/or latching element broken

68 22 39 2068367/1 November 2, 2022.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A5 Cabriolet	2019 – 2024	All	Not Applicable

## Condition

### Customer states:

The wind deflector no longer installs correctly. It will not remain secure when installed.

### Workshop findings:

The wind deflector bearings and / or latching elements are broken preventing a secure installation.

## Technical Background

If the wind deflector is incorrectly installed, removed, or the folding – unfolding sequence is not strictly adhered to according to the specific instructions in the owner’s manual the wind deflector bearings and latching elements are broken and the wind deflector can no longer be securely installed.



*Figure 1. The wind deflector bearing pin is broken off in the mount.*



# Technical Service Bulletin

---

Figure 2 shows the broken wind deflector bearing on the deflector.



*Figure 2. The wind deflector bearing pin is broken off of the deflector structure.*

Figure 3 shows the broken pieces of the wind deflector bearing when the broken pieces are removed.



*Figure 3. Removed pieces of the broken wind deflector bearing pin.*

## Production Solution

Not applicable.



# Technical Service Bulletin

---

## Service


Small parts kit 8W7 898 174 is available to replace the damaged components of the wind deflector. The wind deflector need not be replaced entirely in these cases.

This damage is caused due to outside influence. Replacement of the wind deflector or the small parts kit is not to be claimed under warranty. Counsel the customer as to the specific folding/unfolding sequence of the wind deflector to avoid the recurrence of this damage.

## Warranty

This damage is due to outside influence and is not covered by any Audi Warranty.

## Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
8W7898174	 Small parts kit	1



# Technical Service Bulletin

---

## Additional Information

All parts and service references provided in this TSB (2068367) are subject to change and/or removal.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.