



STAR ONLINE PUBLICATION



Case Number: S2108000219 – REV. A

Release Date: October 2022

Symptom/Vehicle Issue: Intercooler I/C Coolant Temp Missing On The Performance Page App

Technician Observation: The customer may notice I/C coolant temp not showing on the performance page of radio screen.

Discussion: The I/C temp is supposed to display on both cluster and radio screen in the performance page app.

1. Verify if the I/C coolant temp displays on the cluster correctly
2. If the I/C temp is blank on performance page of radio screen, but displays ok on the cluster, the issue is radio software related.

Do not replace the radio head unit for this concern. Software fix for this issue is planned in Q1 2023.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.