

GPOP - Issue Review System

Part Number: 68289209A\$

Part Description: SENSOR, Battery

Issue Description: Before replacing the intelligent battery sensor (IBS) on 2022 MY vehicles, please contact FCA Redacted Content.

If no response in 15 minutes, proceed with repair. Please send pictures of the top of the unit, with a description of the failure, to FCA Redacted Content.