

GPOP - Issue Review System

Part Number: 6KM741A6A\$, 6KM741X7A\$, 6KM741T5A\$, 6KM741D4A\$

Part Description: BUCKLE ASSY, Seat Belt, Left or Right (Front Row)

Issue Description: Before ordering a new buckle part, ensure connector from buckle to wiring harness is fully seated. If not fully seated, this throws an intermittent airbag light on and occupant unbuckled HMI message.

Airbag / seat belt light may be falsely turned on if seat buckle connector is not fully seated. Instead of replacing buckles, first check connection.

Step 1: Unplug buckle from body harness.

Step 2: Re-connect buckle connector to body harness.

Step 3: Ensure connection is fully made and the airbag / seat belt lights are no longer on.

Step 4: If lights remain on, replace buckle.
