

GPOP - Issue Review System

Part Number: 68346540A\$

Part Description: ELEMENT, Heated Seat, Seat Cushion

Issue Description: Before deciding to replace the heater mat, please check heater mat resistances at the pigtail:

- Between pin 1-4: (2.03 to 2.49 Ohms)
- Between pin 2-3: (9kOhms - 11 kOhm)

Also, check heater mat connection to seat harness.

For WL (Grand Cherokee L and Grand Cherokee) equipped with this heater mat that require replacement. DO NOT tear off the heater mat from the foam cushion, instead the whole foam-heater mat assembly must be replaced. Please send back heater mat to Quality team at Stellantis.

In case of questions please contact:
FCA Redacted Content