

SERVICE BULLETIN 599 - STARTER SOLENOID AND REAR GRAB HANDLE TORQUE CHECK



Notice Information

Ref	22715
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Parts / Accessories Coordinator, Sales Executive, Clothing Sales, Sales Manager, Aftersales Manager, Service Leader / Advisor, Accounts / Admin, Marketing Executive
Subject:	Service/Technical

TOL NOTICE (USCA) – November 4, 2022

TOL Ref. #22715-SVC

SERVICE BULLETIN 599 – STARTER SOLENOID AND REAR GRAB HANDLE TORQUE CHECK

Dealers are requested to check the torque of the starter solenoid cable fixings and the rear grab handle fixings as described in the procedure below.

Subject: Starter Solenoid and Rear Grab Handle Torque Check				
Bulletin Number	Models Affected	VIN Range		Markets Affected
599	Tiger 900 Tiger 900 GT Tiger 900 GT Pro Tiger 900 Rally Tiger 900 Rally Pro Tiger 900 GT – LRH (Low Ride Height) Tiger 900 Bond Edition Tiger 850 Sport	From AZ6646	To BF1279	All Markets except Brazil and India

The complete Service Bulletin 599 and instructions can be found attached and at the TriumphOnline.net (TOL) [Service Bulletin Page](#). Please print and ensure that all relevant staff in your dealership/market are familiar with the action.

Warranty Claim Instructions					
Bulletin Number	Model	Fault Code	Repair Code	Description	Repair Time Allowance
599	Tiger 900 Tiger 900 GT Tiger 900 GT Pro Tiger 900 Rally Tiger 900 Rally Pro Tiger 900 GT-LRH (Low Ride Height) Tiger 900 Bond Edition Tiger 850 Sport	023080999	99599	Torque the fixings for the starter solenoid cables and the rear grab handle.	0.1 Hours

Reminder: use the "[VIN Enquiry](#)" function within TOL to search for any outstanding bulletins or recalls whenever a new bike arrives, or a Triumph owner visits your dealership.

Customer Contact Instructions

Motorcycles in the affected VIN range must be modified prior to delivery to the customer, or at the next visit to the dealership.

-

-

Notes:

- Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory.
- Unmodified motorcycles can be identified by checking the 'VIN Enquiry' on www.triumphonline.net.

-

-

If you have any additional questions, please contact your Triumph Regional Manager or Triumph Customer Support at (888) 284-6288.