

Subject		Market	
Front Hub & Bearing Noise		USA	
Service Category	Section		
Drivetrain	Axle/Differential		
Applicability			
19-22MY Camry / Camry HV			

APPLICABLE VEHICLES

2019-2022	Camry	2019-2022	Camry HV
-----------	-------	-----------	----------

CONDITION

Some 2019-2022 model year Camry / Camry HV vehicles may exhibit an abnormal noise from the front of the vehicle over 20 mph.

RECOMMENDATIONS

Confirm there is an abnormal noise coming from the front of the vehicle, some customers describe the noise as a roaring type noise.

Confirm the vehicle meets the following criteria:

- Mileage is under 5,000 miles
- No previous repairs or accidents
- Noise is due to the left/right/both front hubs and bearings

If the vehicle meets the above criteria, please recover the front hubs and bearings and submit a Dealership Product Report (DPR) including a video of the condition.

If the vehicle does not exhibit an abnormal noise OR does not meet the above criteria, please proceed to diagnose the vehicle using the applicable repair manual.

LINK REFERENCES

This Tech Tip does not contain any link references