



NUMBER: 18-044-22

GROUP: 18 - Vehicle Performance

DATE: March 1, 2022

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

SUBJECT:

Flash: Powertrain Control Module (PCM) Updates

OVERVIEW:

This bulletin involves reprogramming the PCM with the latest available software.

The PCM software update is being released as a generic release to support PCM replacement only in service.

MODELS:

2022 (WS) Grand Wagoneer/Wagoneer

NOTE: This bulletin applies to vehicles within the following markets/countries: North America and EMEA.

NOTE: This bulletin applies to vehicles equipped with a 5.7L V8 Engine With Etorque (Sales Code EZL).

DISCUSSION:

There are no fixes for customer facing symptoms contained in this software.

CAUTION! Only if PCM replacement is necessary should the module need updated with this software. Refer to the detailed service procedures available in DealerConnect> Service Library under: Service Info> 08 - Electrical / 8E - Electronic Control Modules / Module, Powertrain Control (PCM) / Removal and Installation.

POLICY:

Information Only