

## **GPOP - Issue Review System**

**Part Number:**

05179091A\$, 05179091A\$,

**Part Description:**

---

Gasket, Cylinder Head Cover

---

**Issue  
Description:**

For US dealers, and 21-22 model year vehicles only. If replacing the cylinder head cover/fuel injector harness gasket due to an oil leak, please also replace the following components:

1. 68445548A\$ - Cover, Cylinder Head (includes gasket)
2. 05179087A\$ - Housing, Rocker Arm
3. 68005453A\$ - Bolt and Grommet, Cylinder Head Cover to Cylinder Head (qty 6)
4. 05114418A\$ - Gasket, Rocker Arm Housing

Engineering requires these parts for analysis to determine root cause of the leak. Once the repairs are complete, please contact FCA Redacted Content, to set up a Fast Track for the return of the parts.