



Bulletin No.: PIT5962
Published date: 12/13/2022

Preliminary Information

PIT5962 Reflective High Temperature Heat Or Insulating Tape For Wiring Harness Repairs

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
All	All Models	2010 - 2023	All	All	All	All

Involved Region or Country	North America
Condition	When performing certain repairs, such as a wiring harness repair, there maybe a reflective high temperature heat or insulating tape that may need to be replaced. In some cases, the part number for this type of tape can be difficult to locate, which is the reason for this PI.
Cause	Difficulty locating the part number for a reflective high temperature heat or insulating tape.

Correction:

If a reflective high temperature heat or insulating tape is needed then use GM part number 10184916.

Parts Information

Description	Part Number	QTY
Insulating Tape	10184916	2"x20' roll

Version History

Version	1
Modified	12/13/2022 - Created on.

