
Reference	SSM75913
Models	Range Rover Sport / L494
Title	Range Rover Sport SVR Carbon Fiber Hood Finish Repair
Category	Body
Last modified	13-Jan-2023 00:00:00
Symptom	106000 Paint/Finish

Content

Issue: The clearcoat paint finish on the "exposed carbon fiber look" section of the hood might wrinkle, discolor and or peel off. This applies only to Range Rover Sport vehicles with the "carbon pack" option.

Cause: This may be caused by UV damage or failure of the adhesion promoter paint layer between the carbon fiber gelcoat resin and the clearcoat paint.

Action: This hood finish concern can be repaired without the need to replace the carbon fiber hood. A formal workshop procedure is being created. Should you have a question or concern with a hood that exhibits this concern, please send an email to jbenne87@jaguarlandrover.com.

anBhdHRicnM7MjAyMy0wM0wMV0xtNDowNjpo0OC43MjBaOzEzNi4yMjYyNzluMT13Ow==