

9100116

01/06/2023

MY 21-23 JL

## **GPOP - Issue Review System**

**Part Number:** 68443442A\$,

**Part Description:** Valve - Coolant

**Issue** JL PHEV Hoses to 3-Way valve coolant hoses misroute causes P0E80-00. Check hose routing as outlined in Star Online  
**Description:** Publication S2208000205 or on a known good vehicle before replacing valve. Routing hoses correctly will likely fix the issue.