

GPOP - Issue Review System

Part Number: 68259561A\$

Part Description: Front Drive Shaft

Issue Description: If replacing DT 5.7L front propeller shaft for concerns of a noise, please contact FCA Redacted Content prior to ordering part to create a FasTrack for return to analyze. If no response in 15 min, proceed with repair.