

97 12V charging socket/cigarette lighter socket not working

90 23 04 2069416/1 February 10, 2023.

| | Model(s) | Year | VIN Range | Vehicle-Specific Equipment |
|---|-------------------|-------------|-----------|----------------------------|
| A | All Audi Vehicles | 2018 – 2024 | All | Not Applicable |

Condition

Customer states:

The 12V socket and/or the cigarette lighter are not working.

Workshop findings:

During diagnosis, the fuse to the 12V outlet is found blown.

The following DTC may is stored in the onboard supply control unit, J519 (address word 0009):

• DTC U141500 Terminal 30-5, open circuit.

Technical Background

Devices connected to the 12V sockets must not exceed a power rating of 120W. Additionally, it is not permitted to connect multiple devices to the 12V sockets in the vehicle even with an adapter (refer to vehicle Owner's Manual).

Due to an excessive load, the overload protection in the adapter or component melts and causes a short circuit, which trips the vehicle fuse.

Production Solution

Not applicable.

Service

Please check whether a short circuit can be measured at the 12V sockets. If no short circuit is detected replace the fuse and advise the customer of the power ratings of the 12V sockets.

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Page 1 of 2

© 2023 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Additional Information

All parts and service references provided in this TSB (2069416) are subject to change and/or removal.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

© 2023 Audi of America, Inc.

Page 2 of 2

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.