

**On-car analysis list from February 20th, 2023
please contact VW Helpline before attempting repair**

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Tiguan	21-23	All	All	MIL-on P0456 P0442	Customer states MIL-on, fault P0456 and/or P0442 stored in ECM memory (Reference worksheet "Tiguan EVAP Leak - Questionnaire" before creating/calling Group TAC)
	Atlas, Atlas Cross Sport	23	3.6L CDVC	All	MIL-on P0461	Customer states MIL-on, fault P0461 stored in ECM memory (Reference worksheet "Atlas P0461 - VIN4APIN - Customer Questionnaire" before creating/calling Group TAC)
Chassis	Tiguan, Taos	22-23	All	All	Front Drive Shaft Noise	Noise from front end while driving (popping, grinding, knocking, swishing, clicking, thumping and/or creaking noise)
Electri	Tiguan, Jetta	19	All	All	Door Harness	Customer states MIL-on/Airbag light, fault U019900 and/or B101715 stored in ECM/Airbag memory
	Tiguan	22-23	All	All	Seat Belt	Customer states seat belt won't retract