

# WNQ2 Workshop campaign – Check rear lid and rework if necessary

---

## WNQ2 Workshop campaign - Check rear lid and rework if necessary

ID Number	WNQ2
Models	Taycan 4S (Y1A) / Taycan Turbo (Y1A) / Taycan Turbo S (Y1A)
Model Years	2020
VIN List	Attached
Number of Affected VINs	225
Issue Description	<p>On the affected vehicles, there is a possibility that clinch points on the rear cover in the area of the rear spoiler were not fitted according to the specifications during production.</p> <p>Over the life of the vehicle, cracks can occur at the clinch points and lead to water leaking into the rear lid/luggage compartment.</p> <p>For this reason, the rear cover of the affected vehicles must be checked and reworked depending on the result of the check.</p>
What Dealers Should do	Please arrange for this measure to be carried out as soon as possible on affected vehicles. <b>As of the time of this posting (2/24/23), the repair is immediately available.</b>
TI Number	<a href="#">No. 208-20</a>

### Required parts

Part number	Designation	Quantity/vehicle**	Parts return*
00004330532	Sealing compound	0.1 piece	No
or			
WNQ20000001***	Sealing compound	1 pc	No

WNQ2 Workshop campaign – Check rear lid and rework if necessary

and

WNQ20000002\*\*\*\*                      Expendable items                      1 pc                      No

\* The parts must be stored until such a time as the related warranty or campaign claim has been credited . If a barcode is generated with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the replacement parts process or be scrapped.

\*\*For the leak test of the rear lid (scope 1), no parts and expendable materials are required.

\*\*\*For warranty processing in the warranty claim, the part number WNQ20000001 with the designation "Body sealant" can be invoiced as an additional part.

\*\*\* \*For warranty processing, the Part No. WNQ20000002 with the designation "Consumable material" can be invoiced as an additional part in the warranty claim. Maximum cost: \$2.10.

## Warranty processing

Validity:

This workshop campaign will be carried out up to January 19, 2028 and will be closed on that date.

Please note that warranty claims can only be processed up to this date.

Scope 1:

Damage Code	WNQ2 66 000
Repair Code	1
Labor time	133 TUs

Scope 2:

Damage Code	WNQ2 66 000
Repair Code	1
Labor time	158 TU

Scope 3:

Damage Code	WNQ2 66 000
Repair Code	1
Labor time	174 TU

Please enter the campaign carried out in the warranty and maintenance booklet for the vehicle.

## Customer mobility

If requested, mobility for the affected customer can be guaranteed by offering a suitable replacement vehicle.

Please invoice this additional service via WWS with the campaign scope.

WNQ2 Workshop campaign – Check rear lid and rework if necessary

## **Attachments**

1. [VIN\\_List\\_Report\\_WNQ2\\_2023-02-24\\_V2.xlsx](#)