

HVAC Vents Blow Warm Air When Not Expected

Customer Voice:

- A customer may complain that either the left hand or right hand HVAC fascia vents blows warm air when not selected.

Technical Description:

- This may be caused by either LIN Bus A or B for the stepper motors not transmitting data, with relevant DTCs stored in the HVAC module.

Status:

- SSM 75891 has been published to provide instructions for testing the LIN Bus circuit.
- Should a customer express a concern, please refer to this SSM.
- Upon completion of the SSM procedures, please submit an EPQR with the data and results listed in the SSM.
- Should further diagnostic support be required, please submit a TA case so support can be provided.

22-23MY Range Rover (L460)

