

SERVICE BULLETIN SPARES KIT REMINDER




Notice Information

Ref	23672
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Parts / Accessories Coordinator, Sales Executive, Clothing Sales, Sales Manager, Aftersales Manager, Service Leader / Advisor, Accounts / Admin, Marketing Executive
Subject:	Service/Technical

TOL NOTICE (US&CA) – February 24, 2023 TOL Ref. # 23672

Service Bulletin Spares Kit Reminder

It has come to our attention that some spares kits for SB600 have been shipped to dealers missing the replacement fastener which secures the detent arm to the crankcase.



If you receive any kits without the replacement fixing, the original can be reused. You must clean the threads of the bolt and apply Threebond 1375B or an equivalent locking compound before refitting as per the Service Bulletin Instruction.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.