
Technical Service Bulletin



40 Squeaking noises when steering or maneuvering

40 23 51 2023187/7 March 23, 2023. Supersedes Technical Service Bulletin Group 40 number 21-30 dated December 22, 2021, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All Audi Vehicles	2009 – 2024	All	Not Applicable

Condition

REVISION HISTORY			
Revision	Date	Purpose	
7	-	Revised header (Added Model Years)	
6	12/22/2021	Revised header (Added Models and Model Years)	
5	12/13/2016	Revised header (Added Model Year)	

Customer states:

Squeaking noises are heard when the steering wheel is turned or maneuvered. The noises may be more prevalent in wet weather.

Technical Background

The folds of the outer rubber boots on the front axle shafts may come in contact with each other when the steering wheel is turned, causing squeaking noises. These noises are more likely to occur when the vehicle is new. The volume and occurrence of the noise will dissipate after a short break-in period.

Production Solution

Not Applicable.

Service

This is a normal condition. Explain the *Technical Background* to the customer.

Do not replace any parts, as replacing parts will not correct the concern. Needlessly replaced parts will be debited.


Warranty

This TSB is informational only and not applicable to any Audi warranty.

© 2023 Audi of America, Inc.

Page 1 of 2

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Additional Information

All parts and service references provided in this TSB (**2023187**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair. **©2023 Audi of America, Inc.** All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.