

WPB0 Workshop Campaign - Replace screw connection for backrest frame on front seat frame

WPB0 Workshop Campaign - Replace screw connection for backrest frame on front seat frame

ID Number	WPB0
Models	Taycan (Y1A, Y1B, Y1C)
Model Years	2021-2022
VIN List	Attached
Number of Affected VINs	4
Issue Description	<p>On the affected vehicles, there is a possibility that the screw connection of the backrest frame to the seat frame at the front has not been carried out correctly.</p> <p>Therefore, the screw connection does not comply with Porsche's internal specifications.</p> <p>For this reason, the screw connection of the backrest frame to the seat frame at the front must be replaced on the left or right depending on the scope of action.</p>
What Dealers Should do	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles. As of the time of this posting, the repair is immediately available. Parts can be ordered as normal via PPL.</p>
TI Number	No. 19-23
Customer Notification	To be published at a later date.

Required parts

Part number	Designation	Quantity/vehicle	Parts return*
9A7007867	Hexagon socket head bolt M10 x 14	4 pieces	No
9A700748300	External hexalobular bolt M10 x 28	4 pieces	No

WPB0 Workshop Campaign - Replace screw connection for backrest frame on front seat frame

*The parts must be stored until such time as the related warranty or campaign claim has been credited. If a barcode is generated with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the replacement parts process or be scrapped.

Warranty processing

Validity:

This workshop campaign will be carried out up to March 1st, 2028 and will be closed on that date.

Please note that warranty claims can only be processed up to this date.

Scopes 1 and 2:

Damage Code	WPB0 66 000
Repair Code	2
Labor time	112 TU

Please enter the campaign carried out in the warranty and maintenance booklet for the vehicle.

Customer mobility

If requested, mobility for the affected customer can be guaranteed by offering a suitable replacement vehicle. Please invoice this additional service again via WWS with the campaign scope.

Attachments

1. [VIN_List_Report_WPB0_2023-03-03_V2.xlsx](#)