



Preliminary Information

PIT5883J Vehicles Built Without or Disabled Options/Heated Vented Seats/Steering Wheel/Front Rear Park Assist /Wheel Liners/Column Lock/Rocker Protectors/Express Up Rear Windows/Adaptive Super Cruise/120V Power Outlet/Lane Change/Side Blind Zone/Rear Cross Traffic Alerts

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Enclave	2022 - 2023	All	All	All	All
Buick	Encore GX	2022 - 2023	All	All	All	All
Cadillac	CT4	2022 - 2023	All	All	All	All
Cadillac	CT5	2022 - 2023	All	All	All	All
Cadillac	Escalade Models	2022 - 2023	All	All	All	All
Cadillac	XT4	2022 - 2023	All	All	All	All
Cadillac	XT5	2022 - 2023	All	All	All	All
Cadillac	XT6	2022 - 2023	All	All	All	All
Chevrolet	Blazer	2022 - 2023	All	All	All	All
Chevrolet	Camaro	2022 - 2023	All	All	All	All
Chevrolet	Colorado	2022	All	All	All	All
Chevrolet	Corvette	2022 - 2023	All	All	All	All
Chevrolet	Equinox	2022 - 2023	All	All	All	All
Chevrolet	Malibu	2022 - 2023	All	All	All	All
Chevrolet	Silverado LTD (RPO J21, VIN Digit 5 = Y or W)	2022	All	All	All	All
Chevrolet	Silverado 1500 New (RPO J22, VIN Digit 5 = D or A)	2022	All	All	All	All
Chevrolet	Silverado 1500	2023	All	All	All	All
Chevrolet	Silverado 2500/3500HD	2022 - 2023	All	All	All	All
Chevrolet	Suburban	2022 - 2023	All	All	All	All
Chevrolet	Tahoe	2022 - 2023	All	All	All	All
Chevrolet	Trailblazer	2022 - 2023	All	All	All	All
Chevrolet	Traverse	2022 - 2023	All	All	All	All
GMC	Acadia	2022 - 2023	All	All	All	All
GMC	Canyon	2022	All	All	All	All
GMC	Sierra Limited (RPO J21, VIN Digit 5 = 8 or 9)	2022	All	All	All	All
GMC	Sierra 1500 New (RPO J22, VIN Digit 5 = U or H)	2022	All	All	All	All

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
GMC	Sierra 1500	2023	All	All	All	All
GMC	Sierra 2500/3500HD	2022 - 2023	All	All	All	All
GMC	Terrain	2022 - 2023	All	All	All	All
GMC	Yukon Models	2022 - 2023	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	R6X, R7N, RFZ, 02O, 04O, 00G, 00N, 00R, 00S, 00U, 00V, 00Y, 08R, 07Z, and/or 00Z
Condition	<p>This is an informational PI to bring awareness to certain vehicle options being disabled. Please be aware that some vehicles, identified by an RPO code, are built with the following option(s) disabled:</p> <p>Front and/or Rear Park Assist disabled - RPO's 00Z or 00Y Heated Steering Wheel disabled - RPO 00G Heated/Vented Seats disabled - RPO 00V or 00R Not equipped with front seat cushion ventilation RPO 04O Not equipped with Electronic Steering Column Lock RPO R7N Not Equipped with Rocker Protector RPO R6X Not Equipped with Rear Wheelhouse Liner RPO RFZ Not Equipped with 2ND Row Express Up Window Control RPO 00N Not Equipped with Adaptive Cruise Control and Enhanced Auto Emergency Braking RPO 07Z Not Equipped with Super Cruise Control RPO 00U and/or 02O Not Equipped with 120V AC Power Outlets RPO 08R Not equipped with Lane Change Alert with Side Blind Zone Alert and Rear Cross Traffic Alert RPO 00S</p>
Cause	Parts shortage

Correction:

If you have a vehicle with any of these RPO's and a complaint that the option does not work do not perform any repairs at this time. Please reference the following GM Global Connect messages for more information:

Front and Rear Park Assist Disabled - Reference Number: GCUS-14-1518 supersedes GCUS-17-429 (Canada GCCA-9-4306) - Retrofit Kit Planned

Heated Steering Wheel Disabled - Reference Number: GCUS-14-1509 supersedes GCUS-17-425 (Canada GCCA-9-4310) - Retrofit Kit Planned

NOTE: On vehicles with Heated Steering Wheel Disabled RPO 00G, DTC(s) U152B, U1530 and/or U0229 may be set and should be ignored. These DTC's do not turn on any warning messages or lights.

Heated/Ventilated Seats Disabled - Reference Number: GCUS-14-1543 supersedes GCUS-17-424 (Canada GCCA-9-4307) - Retrofit Kit Planned

NOTE: On vehicles that have not received the Heated/Vented Seat retrofit kit, if N222386380 is completed it could enable the heated/vented seat switches. Even though the switches appear to be operational, the heated/vented seats will not be operational until the retrofit kit is installed. Do NOT perform the heated/vented seat retrofit unless there is an open bulletin listed in VIS for the vehicle.

Not equipped with front seat cushion ventilation RPO 04O - Reference Number: GCUS-14-1576 - Retrofit Kit Planned

Not equipped with Electronic Steering Column Lock RPO R7N - Reference Number: GCUS-14-1576

Not Equipped with Rocker Protector RPO R6X - Reference Number: GCUS-14-1587

Not Equipped with Rear Wheelhouse Liner RPO RFZ - Reference Number: GCUS-14-1573

Not Equipped with 2ND Row Express Up Window Control RPO 00N

Not Equipped with Adaptive Cruise Control and Enhanced Auto Emergency Braking RPO 07Z - Reference Ordering Workbooks / Dealer Ordering Guides

NOTE: NO retrofit kit is planned to add Adaptive Cruise Control and Enhanced Auto Emergency Braking on vehicles build with RPO 07Z

Not Equipped with Super Cruise Control RPO 00U and/or 02O - No retrofit kits

Not Equipped with 120V AC Power Outlets RPO 08R - Reference Number: GCUS-14-1644

Not equipped with Lane Change Alert with Side Blind Zone Alert and Rear Cross Traffic Alert RPO 00S - Reference Number: GCUS-17-452 - Retrofit Kit Planned

Additional SI Keywords

110, seat, volt, voltage,

Version History

Version	10
Modified	01/10/2022 - Created on. 01/18/2022- Updates to Condition and Model sections 01/26/2022 - Update to correction section to add Canada Global message numbers 08/11/2022 - Update to the model list 08/18/2022 - Updates to the Model list, Title, Additional Options, Condition and Correction sections 09/13/2022 - Updates to the Title, Additional Options, Condition and Correction sections 11/01/2022 - Update to the Models, Title, Additional Options, Condition and Correction sections 12/15/2022 - Update to the Title, Additional Options, Condition and Correction sections 02/22/2023- Update to the Title, Additional Options, Condition and Correction sections 03/16/2023 - Updated to remove words from title due to translation limitations

