



Preliminary Information

PIP5909 2024 T1XX Truck 6.6L ECM Restriction (L5P)

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 2500 and 3500	2024	All	All	6.6 LSP	All
GMC	Sierra 2500 and 3500	2024	All	All	6.6 LSP	All

Involved Region or Country:	North America
Condition:	As part of our ongoing quality improvement efforts the Engine Control Module (ECM), part number 12728504, will be placed on a parts restriction through the Product Quality Center (PQC).
Cause:	This parts restriction will assist Engineering with product feedback.

U.S Dealers:

Please contact the Product Quality Center (PQC) by opening a new case via Dealer Case Management (DCM).

From the DCM home page, click on "New PQC Case" found on the Technical Assistance tab.

Then in Global Connect, click on the Support/Chat tab, TAC-PQC Tab, PQC - Parts Restrictions Templates to download the appropriate PQC - Parts Restrictions Template and save a copy to your computer.

You can attach a copy of the template to your PQC Case.

Dealers in Canada :

If your diagnosis leads to a possible part replacement, please contact the PQC by email at PQC@gm.com or by calling 1-866-654-7654 to receive the PQC - Parts Restriction Template then, return the completed Parts Restriction Questions for engineering review.

Note: Do not clear any DTCs prior to contacting the PQC.

Note: Please be advised that engineering may request a GDS2 session log. Please have the GDS2 session available if requested.

Parts Information

Description:	Part Number:	Quantity:
ECM (E42)	12728504	1

Version History

Version	1
Modified	03/30/2023 - Created on.

