

Subject

Protector Heater Seal Needed When Replacing Evaporator Core or Radiator Heater Unit Sub-Assy.

Market

USA

Service Category

Vehicle Interior

Section

Heating/Air Conditioning

Applicability

2016 - 2023 Tacoma

APPLICABLE VEHICLES

2016-2023

Tacoma

CONDITION

Electronic Parts Catalog (EPC) does not include notes requiring ordering the Protector Heater seals when replacing the air conditioning Evaporator Core (87511- #####) or Radiator Heater Unit Sub-Assembly (87107- #####).

RECOMMENDATIONS

When replacing the air conditioning Evaporator Core (87511- #####) or Radiator Heater Unit Sub-Assembly (87107- #####), the Protector Heater (87286 - #####) seals are not reusable and NEW Protector Heater seals must be used. Best practice is to order the protector seals at the same time as the Evaporator Core or the Radiator Heater Unit Sub-Assembly to prevent delays in repairing the vehicle.

The screenshot displays the Toyota Electronic Parts Catalog (EPC) interface. On the left, an exploded view diagram of the heater unit assembly is shown with various components labeled with part numbers. On the right, a table lists the parts:

PNC	Description	Part Number	Qty	Usage	Fdate	Frev
87173D	PROTECTOR HEATER	87268-54110	01	GRN305,310,325,330,TRN245,265	2019-09	

LINK REFERENCES

This Tech Tip does not contain any link references

[Click here to enter text.](#)

Expires on 03/06/2024

© 2023, Toyota Motor Sales, USA

Page 1 of 1