

Subject 2017-2020 Yaris Sedan (Mexico Production) Squeak Noise Over Bumps (Puerto Rico Only)		Market USA
Service Category Suspension	Section Front Suspension	
Applicability 2017-2020 Yaris Sedan Mexico Production		

APPLICABLE VEHICLES

2017-2020

Yaris SD MEX-Prod

CONDITION

Some 2017-2020 Yaris Sedan (Mexico Production) vehicles exhibit a squeak type noise from the front suspension over bumps. This document applies to Puerto Rico Region vehicles only.

RECOMMENDATIONS

This issue is currently under investigation. Please contact your region FTS for any 2017-2020 Yaris Sedan (Mexico Production) vehicles that exhibit this squeak type noise from the front suspension over bumps (Puerto Rico Only). If it is a weekend or holiday, continue with diagnosis and repair. Please save all parts and/or details and contact your region FTS on the next available workday.

LINK REFERENCES

1. [FRONT SUSPENSION: FRONT STABILIZER BAR: COMPONENTS; 2016 - 2020 MY Yaris HB MEX-Prod Yaris R Yaris SD MEX-Prod \[07/2015 - ???????\]](#)
2. [FRONT SUSPENSION: FRONT STABILIZER BAR: REMOVAL; 2016 - 2020 MY Yaris HB MEX-Prod Yaris R Yaris SD MEX-Prod \[07/2015 - ???????\]](#)
3. [FRONT SUSPENSION: FRONT STABILIZER BAR: INSTALLATION; 2016 - 2020 MY Yaris HB MEX-Prod Yaris R Yaris SD MEX-Prod \[07/2015 - ???????\]](#)