

Subject Protector Heater Seal Needed When Replacing Evaporator Core or Radiator Heater Unit Sub-Assy.		Market USA
Service Category Vehicle Interior	Section Heating/Air Conditioning	
Applicability 2016 - 2023 Tacoma		

APPLICABLE VEHICLES

2016-2023	Tacoma
-----------	--------

CONDITION

Electronic Parts Catalog (EPC) does not include notes requiring ordering the Protector Heater seals when replacing the air conditioning Evaporator Core (88511- #####) or Radiator Heater Unit Sub-Assembly (87107- #####).

RECOMMENDATIONS

When replacing the air conditioning Evaporator Core (88511- #####) or Radiator Heater Unit Sub-Assembly (87107- #####), the Protector Heater (87268 - #####) seals are not reusable and NEW Protector Heater seals must be used. Best practice is to order the protector seals at the same time as the Evaporator Core or the Radiator Heater Unit Sub-Assembly to prevent delays in repairing the vehicle.

The screenshot shows the Toyota Electronic Parts Catalog (EPC) interface. On the left is a detailed parts diagram for the '1508-1 AUTO AIR CONDITIONER' with various components labeled with part numbers. On the right is a table with the following data:

PNC	Description	Part Number	Qty	Usage	Fdate	Frev
87173D	PROTECTOR HEATER	87268-54110	01	GRN305,310,325,330,TRN245,265	2019-09	

LINK REFERENCES

This Tech Tip does not contain any link references