

On-car analysis list from April 18th, 2023
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Tiguan	21-23	All	All	MIL-on P0442	Customer states MIL-on, P0442 stored in ECM memory (Untouched vehicle)
	All	22	All	All	MIL-on P2402	Customer states MIL-on, fault P2402 stored in ECM memory (Florida vehicle only)
	Jetta GLI	23	2.0T DKFA	All	Fuel Line Rattle	Customer states rattle from beneath the vehicle (Root cause is fuel line) (Untouched vehicle)
	Atlas, Atlas Cross Sport	23	3.6L CDVC	All	MIL-on P0461	Customer states MIL-on, fault P0461 stored in ECM memory
Chassis	Tiguan, Taos	22-23	All	All	Front Drive Shaft Noise	Noise from front end while driving (popping, grinding, knocking, swishing, clicking, thumping and/or creaking noise)
Electric	Jetta	19	All	All	Door Harness	Customer states MIL-on/Airbag light, fault U019900 and/or B101715 stored in ECM/Airbag memory
	ID.4	23	All	All	Taillight Condensation	Customer states condensation in the taillights (Untouched vehicle)
	Atlas, Cross Sport, Jetta, Taos, Tiguan	22-23	All	All	Key Battery	Customer states key FOB lock/unlock functions do not work via button press (not KESSY). (Must have B147918 and/or B147A18 in Address 09)
	Tiguan	22-23	All	All	Seat Belt	Customer states seat belt won't retract