

## POWERTRAIN – FUEL SMELL FROM CABIN IN HIGH AMBIENT

### Retailer Voice:

- JLR have received reports of fuel smell being present in the cabin. Cases have been in high ambient regions. Customer may report fuel smell after steady state drive or long idle period.


### Technical Description:

- Under investigation by Engineering

### Status:

- Please check entire fuel system for any abrasions or fuel residue as in TOPIx 310-01B
- At this stage please raise an EPQR for the attention of Engineering and your diagnostic steps.

22-23MY New Range Rover  
23MY New Range Rover Sport  
All Engines



E288850