

Service Bulletin

Bulletin No.: 23-NA-077

Date: April, 2023

TECHNICAL

Subject: Universal Garage Door Remote will not Program Correctly

Ī	Brand:	Model:	Model Year:		VIN:		Engino	Transmission:
			from	to	from	to	Engine:	mansinission.
Ī	Chevrolet	Corvette	2021	2023	_	_	_	_

Involved Region or Country	North America, Europe, Middle East, Israel, Japan, Thailand		
Additional Options (RPOs)	Equipped with RPO UG1		
Condition	Some customers may comment that the Universal Garage Door Opener will not train when correctly following the steps outlined in the Owner Manual.		
Cause	The cause of the condition may be that the instructions differ from the Owner Manual.		
	If you encounter a vehicle with the above concern, do not replace any parts. Instruct the customer to replace step #2 of the <i>Programming the Universal Remote System</i> in the Owner Manual from:		
Correction	 Press and release one of the three Universal Remote system buttons to be programmed. Press and hold the hand-held transmitter button. Do not release the hand-held transmitter button until the indicator light changes from a slow to a rapid flash or continuous light. Then release the hand-held transmitter button. 		
	То:		
	 At the same time, press and hold both the hand-held transmitter button and one of the three Universal Remote system buttons to be used to operate the garage door. Do not release either button until the indicator light changes from a slow to a rapid flash. 		
	The customer can then resume the programming instructions at step #3 in the Owner Manual.		

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information:

Labor Operation	Description	Labor Time		
3487808*	Universal Remote System Program Instruction Update	0.2 hr		
*This is a uniq	ue Labor Operation for bulletin use only.			

Version	1
Modified	Released April 18, 2023

