

GPOP - Issue Review System

Part Number: 68376922A\$, 68376923A\$, 68376924A\$, 68376925A\$, 68376926A\$,
68400404A\$, 68400499A\$, 68400545A\$, 68400554A\$, 68400720A\$,
68400737A\$, 68401379A\$, 68401396A\$, 68401549A\$, 68401895A\$,
68401935A\$, 68440435A\$, 68440438A\$, 68440449A\$, 68474259A\$,
68474744A\$, 68474903A\$, 68475245A\$, 68477135A\$, 68477357A\$,
68536536A\$, 68544665A\$

Part Description: Axle Assembly

Issue Description: Do not replace the Axle for Axle Locker Sensor failure. The parts kit (SENSOR KIT, Axle: 68544629A\$) must be used to repair the Axle Locker Sensor on JL/JT equipped with the M210 and M220 Tru-Lok axles (DSE).