



91 RS monitor not available in MMI

91 23 97 2070387/1 May 22, 2023.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
RS 5, and RS 5 Sportback	2021 – 2023	All	Not Applicable

Condition

Customer states:

The “RS monitor” tile is not available in the MMI main menu although the vehicle is an RS 5.

Technical Background

The RS monitor tile is only available with the virtual cockpit, PR code 9S5 or 9S7.

Production Solution

Not Applicable

Service

The “RS monitor” tile (Figure 1) in the MMI is only available in combination with the virtual cockpit.

The Owner's Manual states that the sport displays are available “depending on the vehicle's equipment”.

Please explain this to the customer.






Figure 1: RS Monitor tile as displayed in the MMI screen.

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Additional Information

All part and service references provided in this TSB (**2070387**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.