

WPC3 Workshop campaign – Re-programming rear spoiler control unit

WPC3 Workshop campaign - Re-programming rear spoiler control unit

ID Number	WPC3
Models	911 GT3 RS (992)
Model Years	2023
VIN List	Attached
Number of Affected VINs	41
Issue Description	<p>Due to a software error in the rear spoiler control unit on affected vehicles, the erroneous warning message "Aerodynamics disrupted" may be displayed intermittently in the instrument cluster when the engine is started.</p> <p>In this case, the warning message disappears automatically after a short time and a fault memory entry is written. The "Active aerodynamics" function is always available in all driving modes despite the warning message.</p> <p>For this reason, the rear spoiler control unit on the affected vehicles must be re-programmed with a corrected data set.</p>
What Dealers Should do	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles.</p> <p>As of the time of this posting (5/10/23), the repair is immediately available.</p>
TI Number	No. 33-23

Required software

PIWIS Tester 3 test software version	41.800.022 (or higher)
--------------------------------------	------------------------

Warranty processing

Validity:

This workshop campaign will be carried out until April 5th, 2028 and will be closed on that date.

Please note that warranty claims can only be processed before this date.

Scope 1:

Damage Code	WPC3 66 000
Repair Code	1
Labor time	31 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

Attachments

1. [VIN_List_Report_WPC3_2023-05-10_V2.xlsx](#)