

POWERTRAIN – P6 PHEV HV BATTERY WILL NOT CHARGE

Customer Voice:

- Customers will be reporting PHEV High Voltage battery will not take a charge.

Technical Description:

- The most likely cause is due to the PHEV emergency cable lock release not returning to the relaxed position.

Status:

- Check the emergency release cable to see if it is extended.
- If you have found cable binding, please replace the cable and submit an EPQR with full details of diagnosis and repair.
- If you still are in need of assistance after checking cable operation, please feel free to open a TA for assistance.

Refer to SSM 75994

22-23MY Range Rover, RR Sport
(PHEV MODELS ONLY)

