

Reference	SSM75994
Models	New Range Rover / L460 New Range Rover Sport / L461
Title	L460/ L461 - P6 PHEV will not charge.
Category	Body
Last modified	04-May-2023 00:00:00
Symptom	112000 Latches/Locks & Security
Attachments	Charge port release.jpg (Charge port release.jpg)
Content	<p><u>Issue</u>: L460/461 PHEV will not take a charge</p>

Cause: JLR has found in cases that the PHEV emergency cable lock release is not returning to the relaxed position.

Action: Check the emergency release cable to see if it is extended. If you have found cable binding, please replace the cable and submit an EPQR with full details of diagnosis and repair.

anBhdHRlcnM7MjAyMy0wNS0wNVQxMjowNToyMj4wMDRaOzEzNi4yMjYyNzluMTA1Ow==